



DEPARTMENT OF CIVIL ENGINEERING
GOVT. ENGINEERING COLLEGE, THRISSUR - 9

Ph: 0487-2322989

05.04.2024

STRUCTURAL STABILITY REPORT OF EXISTING BUILDING AT KIRALOOR
(SALSABEEL GREEN SCHOOL, KIRALOOR VILLAGE, VELUR PANCHAYATH,
CHOWVANNUR BLOCK, WARD NO. IX, SURVEY NO. 108/1, BUILDING NO. 319)
THRISSUR DISTRICT

As Per the request letter from The Manager, Salsabeel Green School, Kiraloor, I have visited the building site. I have inspected One Building. It is of (G+1) Floors Only. It is found that the structural members such as columns are found intact. Non-structural cracks were also not observed on the walls. No cracks were seen on these structural members. Upon Non-destructive (Rebound hammer) testing, the structural concrete is having designed strength. From the inspection & NDT testing, the building is found to be safe under Normal Weather Conditions.

However the following points are noted in connection with the above.

1. Need of safety certificate from fire department is not checked.
2. The other construction quality aspects, especially construction joints, construction of walls etc. are not checked in this investigation
3. In future, any new crack found in the structure, the same should be consulted to a structural engineer and the necessary measures should be taken.
4. The Confirmation for KMBR/KPBR of the Building has not been verified

P P Sivan
Assistant Professor in Civil Engineering
Government Engineering College Thrissur

P P Sivan, M.E (Structures)
Assistant Professor in Civil Engg.
Govt. Engg. College Trichur
Thrissur- 680 003
Mob 984631200
Email-ppsilva@yahoo.com

PRINCIPAL
SALSABEEL GREEN SCHOOL
KIRALOOR

MANAGER
SALSABEEL GREEN SCHOOL
KIRALOOR